

# **ELO Touchscreen Driver Installation**

## **for Windows 8 32/64BIT**



### **REQUIRED ITEMS**


Elo Touchscreen

USB cable

Monitor video (VGA) cable

Computer with a free USB port

## Connecting your Elo Touchscreen to the computer



1. Plug one end of the USB cable into the computer and the other end into the touchscreen.

2. Plug the video cable into the computer.
3. If you have the Elo install CD, wait for setup to launch and skip the next step.
4. You can download the appropriate driver from:

[http://download2.pcamerica.com/drivers/8/Manufacturer/ELO/ELO\\_8.zip](http://download2.pcamerica.com/drivers/8/Manufacturer/ELO/ELO_8.zip)



5. Launch the executable.
6. Select **OK**.



7. Select the location to unzip the files to and then select **Unzip**.



8. Select **OK**.




9. Select **Next**.



10. Put a check in **Install USB Touchscreen Drivers**, then select **Next**.



11. Put a check in **Calibrate ELO Touchscreen monitors**, then select **Finish**.



12. Touch the center of each target as it appears on the screen, starting with the upper left (do not double tap).



13. Tap anywhere on the screen one last time to confirm the cursor follows your finger, then tap on the green check to save the calibration settings.